



Montana Freestanding BSM

Installation



Technique drawing



Explosion drawing

